

## USED TIRE INVENTORY

<i>Lot#</i>	<i>Size</i>	<i>Ply</i>	<i>Tread %</i>	<i>Brand</i>	<i>Price</i>	<i>Notes</i>	<i>Origin</i>
270	*8.3-24	6	60%	Goodyear	\$ 50.00	side wall cut, no rim by scout	CG
135	*9.5-24	4	60%	Powermark	\$ 100.00	weathered, on N6 Gleaner	
159	*9.5-24	4	75%	Bridgestone spade grip	\$ 150.00	off rim by Scout	
167	*9.5-24	6	50%	Treadura TT	\$ 150.00	off rim by Scout	
259	*9.5-24	6	30%	Goodyear	\$ 95.00	No rim, on hillside	CG
166	10.00-16	8	40%	Samson 3 rib	\$ 95.00	off rim by shop	
164	11.00-16	8	40%	Firestone 4 rib	\$ 125.00	off rim by shop	
44	11.2-24	4	35%	Goodyear, on B Farmall	\$ 140.00	West end, by south fence, weathered tires both for \$250	
45	11.2-24	4	35%	Goodyear, on B Farmall	\$ 140.00	West end, by south fence, weathered tires both for \$250	
129	11.2-24	6	20%	Firestone	\$ 100.00	on 6620 JD combine	
283	11.2-24	4	95%	Bridgestone	\$ 200.00	no rim, by scout	CG
122	11.25-25	8	15%	Armstrong implement	\$ 75.00	on N6 Gleaner	
163	11L-15	8	40%	Firestone 4 rib	\$ 90.00	off rim by shop	
49	12.4-24	4	50%	Kelly Springfield	\$ 225.00	on rim west end terrace channel	
50	12.4-24	4	50%	Firestone	\$ 225.00	on rim west end terrace channel	
86	12.4-24	8	NEW	Malhotra (India made)	\$ 300.00	by tarp #1, on right before first gate	
136	12.4-24	8	40%	Armstrong	\$ 100.00	weathered, on N6 Gleaner	
258	12.4-24	6	20%	Goodyear	\$ 75.00	No rim, on hillside	CG
158	12.4-24R		75%	Goodyear	\$ 250.00	off rim by Scout	
24	12.4-38	4	90%	Titan	\$ 500.00	on rim, by IH Scout	
225	12.4-38	4	85%		\$ 300.00	By scout off rim	
265	12.4-38	6	50%	Armstrong	\$ 250.00	dry cracks, boot, by Scout	
137	12.5/80-18	12	40%	Deestone	\$ 115.00	industrial tread	
138	12.5/80-18	12	40%	Deestone	\$ 115.00	industrial tread	
257	12.5/80-18	12	30%	MegaTrak	\$ 75.00	No rim, on hillside	CG
260	12.5/80-18	12	70%	Deestone	\$ 175.00	No rim, on hillside	CG
271	12.5/80-18	10	65%	Goodyear	\$ 100.00	no rim by scout	CG

## USED TIRE INVENTORY

<i>Lot#</i>	<i>Size</i>	<i>Ply</i>	<i>Tread %</i>	<i>Brand</i>	<i>Price</i>	<i>Notes</i>	<i>Origin</i>
272	12.5/80-18	10	65%	Deestone	\$ 100.00	no rim by scout	CG
256	13.6-24	8	50%	Treadura TT	\$ 150.00	No rim, on hillside	CG
60	13.6-36	8	60%	BKT	\$ 300.00	yard	
296	13.6-36	6	15%	Alliance	\$ 100.00	stubble damage, on rim by scout	
297	13.6-37	6	15%	Alliance	\$ 100.00	stubble damage, on rim by scout	
173	13.6-38	6	75%	Titan	\$ 450.00		
266	13.6-38	6	85%	Safemark	\$ 375.00	some dry cracks, by Scout	
35	14.00-24	16	5%	Firestone	\$ 75.00	by IH Scout	
19	14.9-24	6	75%	Safemark	\$ 250.00	on 6 loop rim, on hillside	
46	14.9-24	6	40%	Armstrong	\$ 225.00	on 6 loop rim with inside disc, triangle area	
67	14.9-24	6	30%	Multi trac	\$ 190.00	on west end by IH 815 combine-no rim	
79	14.9-24	6	75%	Safemark	\$ 250.00	on 6 loop rim, on hillside	
94	14.9-24	6	90%	Firestone	\$ 400.00	combine	
125	14.9-24	6	50%	Bridgestone	\$ 150.00	old	
144	14.9-24	6	75%	Armstrong	\$ 375.00	on 8 hole orange wheel below combines	
208	14.9-24	6	50%	Firestone	\$ 200.00	by 8630 JD on hillside	
78	14.9-28	4	30%	Goodyear-good tread	\$ 175.00	combine	
153	14.9-28	6	99%	Titan	\$ 525.00	by IH scout on 9Hole JD rim	
255	14.9-28	4	80%	Goodyear	\$ 350.00	by Scout	CG
273	14.9-28R	10	40%	Firestone	\$ 250.00	no rim by scout	CG
274	14.9-28R	10	40%	Firestone	\$ 250.00	no rim by scout	CG
206	14.9-30R	10	40%	Firestone	\$ 550.00	by 8630 JD on hillside	
207	14.9-30R	10	40%	Firestone	\$ 550.00	by 8630 JD on hillside	
77	14.9-38	6	80%	Alliance	\$ 400.00	on dbl bevel rim	
84	14.9-38	6	80%	Alliance	\$ 400.00	on dbl bevel rim	
204	14.9-46R		45%	Continental	\$ 400.00	by 8630 JD on hillside	
85	15.5-38	6	30%	Goodyear	\$ 200.00		
181	15.5-38	8	10%	No brand	\$ 100.00	on 686 IH on side of hill	
36	16.9-26	10	50%	Goodyear Dynatorque	\$ 250.00	on rim west end terrace channel	

## USED TIRE INVENTORY

<i>Lot#</i>	<i>Size</i>	<i>Ply</i>	<i>Tread %</i>	<i>Brand</i>	<i>Price</i>	<i>Notes</i>	<i>Origin</i>
39	16.9-26	6	50%	Premium	\$ 250.00	on 9 hole rim west end of terrace channel	
111	16.9-26	10	75%	Goodyear	\$ 350.00	in triangle area on 8 hole JD rim	
112	16.9-26	6	30%	Firestone	\$ 125.00	in triangle area on 8 hole JD rim	
117	16.9-26	8	20%	Goodyear (K)	\$ 125.00	weather cracked, 2nd row by balers	
20	16.9-26R	1*	50%	Firestone	\$ 550.00	on JD FWD waffle wheel, triangle area	
21	16.9-26R	1*	50%	Firestone	\$ 550.00	w/tube, no wheel, triangle area	
287	16.9-28	8	30%	Titan	\$ 175.00	no rim, by scout	CG
289	16.9-28	8	30%	Titan	\$ 175.00	no rim, by scout	CG
282	16.9-28	8	25%	Titan	\$ 150.00	no rim, by scout	CG
195	16.9-28R		85%	Firestone	\$ 900.00	Next to 8630 JD on hillside	
61	16.9-30	6	50%	Firestone	\$ 300.00	bare tire, needs patch	
62	16.9-30	6	50%	Firestone	\$ 300.00	bare tire, needs patch	
103	16.9-30	6	20%	Titan	\$ 140.00	in stack of tires up hill	
161	16.9-30	6	50%	Goodyear Dynatorque	\$ 350.00	off rim by Scout	
168	16.9-30	6	75%	General	\$ 450.00	Bare tire on hillside	
244	16.9-30	6	40%	Hi-Power	\$ 200.00	No rim, on hillside	CG
245	16.9-30	6	10%	Goodyear	\$ 100.00	No rim, on hillside	CG
246	16.9-30	6	10%	Titan	\$ 100.00	No rim, on hillside	CG
247	16.9-30	8	20%	Goodyear	\$ 125.00	No rim, on hillside	CG
248	16.9-30	6	30%	Goodyear	\$ 150.00	No rim, on hillside	CG
3	16.9-34	6	50%	Alliance	\$ 275.00	on spin out rim, east gate to tractor yard	
4	16.9-34	6	50%	Armstrong	\$ 275.00	on spin out rim, east gate to tractor yard	
14	16.9-34	6	60%	Powermark	\$ 250.00	on Oliver 1800 n fence	
42	16.9-34	6	75%	Firestone, on rim off tractor	\$ 325.00	4th row, by 806 IH deep tread, tube leaks around stem	
43	16.9-34	8	35%	Alliance, on rim off tractor	\$ 225.00	4th row, by 806 IH good tread, weathered tire, tight air	
57	16.9-34	10	50%	Firestone	\$ 500.00	bare tire w/tube, by scout	
58	16.9-34	10	50%	Firestone	\$ 500.00	bare tire w/tube, by scout	

## USED TIRE INVENTORY

<i>Lot#</i>	<i>Size</i>	<i>Ply</i>	<i>Tread %</i>	<i>Brand</i>	<i>Price</i>	<i>Notes</i>	<i>Origin</i>
222	16.9-38	8	60%	Titan	\$ 550.00	on JD 34" drop dbl. bevel rim	
223	16.9-38	8	60%	Titan	\$ 550.00	on JD 34" drop dbl. bevel rim	
240	16.9-38	6	50%	Firestone	\$ 350.00	No rim, on hillside	
278	16.9-38	6	20%	Goodyear	\$ 150.00	dry cracks, on snap on rim by scout	529
279	16.9-38	6	20%	Goodyear	\$ 150.00	dry cracks, on snap on rim by scout	529
47	18.4-16.1	6	60%	Armstrong Turf Torc Trac	\$ 450.00	included	
48	18.4-16.1	6	60%	Armstrong Turf Torc Trac	\$ 450.00	included	
33	18.4-26	8	60%	Powermark	\$ 400.00	Triangle area above terrace, on rim	
139	18.4-26	10	50%	Armstrong	\$ 500.00	on 6600 JD combine	
140	18.4-26	10	15%	Powermark	\$ 150.00	on 6600 JD combine	
143	18.4-26	10	90%	Goodyear	\$ 500.00	combine	
151	18.4-26	10	75%	Firestone	\$ 650.00	below combines on wheel	
152	18.4-26	10	15%	Goodyear	\$ 125.00	below combines on wheel	
169	18.4-26	8	50%	Safemark	\$ 125.00	weather cracked	
241	18.4-26	10	25%	Firestone	\$ 200.00	No rim, on hillside	
275	18.4-26	10	30%	Firestone	\$ 240.00	no rim by scout	
32	18.4-26R	2*	40%	Goodyear, no rim	\$ 100.00	Triangle area above terrace	
269	18.4-30	10	90%	Farmhand	\$ 500.00	on 10 hole JD rim next to Scout	
97	18.4-34	6	75%	Multi trac	\$ 600.00	by IH scout	
102	18.4-34	6	75%	Firestone	\$ 600.00	in stack of tires up hill	
119	18.4-34		15%	Multi trac - weathered	\$ 125.00	on railed rim	
126	18.4-34	6	85%	Alliance - some dry cracks	\$ 500.00	by IH Scout	
133	18.4-34	8	50%	Safemark spade grip	\$ 250.00	weathered, on L2 Gleaner combine	
134	18.4-34	8	50%	Safemark spade grip	\$ 250.00	weathered, on L2 Gleaner combine	
160	18.4-34	6	85%	Alliance - some dry cracks	\$ 500.00	by IH Scout	
198	18.4-34	8	90%	Goodyear	\$ 650.00	on spinout rim next to 8630 JD on hillside	
230	18.4-34	8	20%	Powermark	\$ 175.00	on IH 9 hole rim on hillside	
231	18.4-34	8	90%	Continental	\$ 650.00	on IH 9 hole rim on hillside	
232	18.4-34	6	10%	Goodyear	\$ 100.00	on IH 9 hole rim on hillside	

## USED TIRE INVENTORY

Lot#	Size	Ply	Tread %	Brand	Price	Notes	Origin
233	18.4-34	8	20%	Mitas	\$ 500.00	on IH 9 hole rim on hillside	
17	18.4-38	8	40%	Goodyear Dynatorque	\$ 300.00	on spin out rim	
83	18.4-38	8	70%	Starmax	\$ 400.00	yard	
120	18.4-38	6	40%	No brand	\$ 350.00	on 9h rim by scout	
165	18.4-38	8	25%	Powermark - dry cracks	\$ 150.00	by IH Scout	
176	18.4-38	6	40%	Armstrong	\$ 450.00	on 5020 JD	
177	18.4-38	6	40%	Armstrong	\$ 450.00	on 5020 JD	
178	18.4-38	8	25%	Goodyear	\$ 300.00	on JD 55 series rim	
191	18.4-38	8	60%	Goodyear rice & cane	\$ 600.00	on 8H JD rim - Next to 8630 JD on hillside	
192	18.4-38	8	60%	Goodyear rice & cane	\$ 600.00	on 8H JD rim - Next to 8630 JD on hillside	
199	18.4-38	8	25%	Goodyear - weather cracked	\$ 200.00	on JD rim next to 8630 JD on hillside	
226	18.4-38	8	50%	Galaxy - tread splitting in 1 area	\$ 200.00	rim	
227	18.4-38	8	50%	Galaxy - tread splitting in 1 area	\$ 200.00	rim	
234	18.4-38	6	40%	Del-nat	\$ 250.00	by IH scout on dbl bevel rim - dry cracks	
249	18.4-38	6	20%	Kelly Springfield	\$ 175.00	No rim, on hillside	CG
254	18.4-38	8	20%	Firestone	\$ 175.00	No rim, on hillside	CG
267	18.4-38	6	25%	Firestone	\$ 250.00	on spinout rim by Scout	
268	18.4-38	6	25%	Firestone	\$ 250.00	on spinout rim by Scout	
300	18.4-38	6	80%	Goodyear Duratorque	\$ 700.00	on salvage 4430 JD	
8	18.4-38R	1*	50%	Firestone	\$ 600.00	on JD step up, by 8640	
10	18.4-38R		40%	Goodyear ultra torque	\$ 400.00	terrace channel, triangle area	
41	18.4-38R		20%	Firestone	\$ 150.00		
68	18.4-38R		50%	GY DT710	\$ 600.00	Scout	
69	18.4-38R		50%	GY DT710	\$ 600.00	Scout	
82	18.4-38R		25%	Galaxy deep tread	\$ 175.00	yard	
210	18.4-38R	10	75%	Cambridge	\$ 400.00	by 8630 JD on hillside	
211	18.4-38R		60%	Firestone - needs boot	\$ 250.00	by 8630 JD on hillside	
217	18.4-38R	1*	75%	Firestone	\$ 600.00	on 9h dual rim	
218	18.4-38R	1*	75%	Firestone	\$ 600.00	on 9h dual rim	

## USED TIRE INVENTORY

Lot#	Size	Ply	Tread %	Brand	Price	Notes	Origin
228	18.4-38R	1*	30%	Field Power - has boot	\$ 200.00	by 8630 JD on hillside, on dbl bevel rim	
235	18.4-38R	141A8	70%	Goodyear DT710	\$ 750.00	by IH scout	
301	18.4-38R		40%	Goodyear	\$ 400.00	on salvage 4430 JD	
30	18.4-42R	2*	40%	Titan	\$ 550.00	on JD step wheels w/ 42" tires (\$1,600 for tires/wheels -30&31)	
31	18.4-42R	2*	30%	Goodyear	\$ 400.00	on JD step up wheels w/42" tires, a few weather cracks on tread	
90	18.4-42R	2*	30%	Firestone	\$ 425.00	by IH scout	
221	18.4-42R	2*	40%	Armstrong	\$ 450.00	bare tire, sidewall weathered	
261							
262	18.4-42R		50%	Firestone	\$ 700.00	No rim, on hillside	
280	18.4-42R		10%	Firestone	\$ 200.00	No rim, on hillside	CG
281	18.4-42R	10	30%	Firestone	\$ 125.00	no rim, hole in sidewall by scout	CG
290	18.4-42R		10%	Firestone	\$ 200.00	No rim, on hillside	CG
276	18.4-46	12	40%	Firestone	\$ 400.00	no rim by scout	456
277	18.4-46	12	40%	Firestone	\$ 400.00	no rim by scout	456
72	18.4-46R	2*	30%	Firestone	\$ 350.00	Naked tire, in 42 inch dual section	
73	18.4-46R	2*	30%	Firestone	\$ 350.00	Naked tire, in 42 inch dual section	
75	18.4-46R	3*	30%	Firestone	\$ 350.00	in 42 inch dual area	
76	18.4-46R	3*	30%	Firestone	\$ 350.00	in 42 inch dual area	
96	18.4-46R	3*	40%	Goodyear	\$ 725.00	by IH scout	
149	18.4-46R	3*	30%	Firestone	\$ 500.00	No rim, on hillside	
263	18.4-46R	3*	90%	Goodyear	\$ 1,250.00	No rim, on hillside	
87	18-4-38	6	30%	Multi trac	\$ 275.00	scout	
291	19.5L-24	10	60%	Goodyear	\$ 350.00	No rim, on hillside	CG
18	20.8-34	8	25%	Firestone	\$ 250.00	off rim by Scout	
25	20.8-34	8	40%	Powermark	\$ 350.00	Naked tire east end tractor yard	
51	20.8-34	10	30%	Brigadier	\$ 200.00	No rim, west end by IH Scout	
53	20.8-34	8	60%	Titan	\$ 600.00	on JD dbl bvl rim, west end by IH Scout	

## USED TIRE INVENTORY

<i>Lot#</i>	<i>Size</i>	<i>Ply</i>	<i>Tread %</i>	<i>Brand</i>	<i>Price</i>	<i>Notes</i>	<i>Origin</i>
74	20.8-34	8	40%	Goodyear	\$ 450.00	Naked tire east end tractor yard	
13	20.8-34R	1*	40%	BF Goodrich	\$ 500.00	On dbl/bvl rim east end tractor yard	
7	20.8-38	10	40%	Firestone Spade grip(rice tire)	\$ 400.00	on JD rim east end of tractor yard	
59	20.8-38	10	40%	Firestone Spade grip(rice tire)	\$ 400.00	on JD rim east end of tractor yard	
89	20.8-38	6	25%	Armstrong	\$ 200.00	on 18-38rim not included, by IH Scout	
162	20.8-38	10	15%	BFG	\$ 125.00	by IH Scout	
172	20.8-38	8	10%	BF Goodrich	\$ 100.00	old	
186	20.8-38		45%	Firestone	\$ 450.00	on JD double bevel rim	
205	20.8-38	10	20%	Firestone	\$ 250.00	by 8630 JD on hillside	
214	20.8-38	8	15%	Kelly Springfield	\$ 100.00	by 8630 JD on hillside	
216	20.8-38	8	25%	Kelly Springfield	\$ 200.00	by 8630 JD on hillside	
236	20.8-38	10	20%	Firestone	\$ 200.00	by IH scout on 10 hole JD dual rim	
121	20.8-38	8	15%	Firestone	\$ 125.00	on silver dbl bevel rim by scout	
145	20.8-38R	3*	45%	Firestone	\$ 800.00	on 18x38 snap on dual JD rim by IH Scout	
171	20.8-38R	?	40%	Safemark	\$ 125.00	old	
179	20.8-38R	147A8	40%	Goodyear DT 710	\$ 400.00	on JD 10 hole rim	
182	20.8-38R	147A8	45%	Goodyear DT 710	\$ 450.00	on JD 10 hole rim	
187	20.8-38R	147A8	50%	Goodyear	\$ 600.00	on JD 10 hole rim	
188	20.8-38R	147A8	50%	Goodyear	\$ 600.00	on JD 10 hole rim	
196	20.8-38R	10	50%	Coop	\$ 800.00	hillside	
197	20.8-38R	3*	25%	Firestone	\$ 400.00	hillside	
250	20.8-38R	1*	25%	Firestone	\$ 325.00	by 8630 JD on dbl bevel JD rim	
251	20.8-38R	1*	25%	Firestone	\$ 325.00	by 8630 JD on dbl bevel JD rim	
252	20.8-38R	1*	25%	Firestone	\$ 325.00	by 8630 JD on 10 hole JD dual rim	
253	20.8-38R	1*	25%	Firestone	\$ 325.00	by 8630 JD on 10 hole JD dual rim	
5	20.8-42R	2*	25%	Firestone	\$ 350.00	bare tire, east gate to tractor yard	
6	20.8-42R	2*	25%	Firestone	\$ 300.00	bare tire, east gate to tractor yard	
80	20.8-42R	2*	40%	Goodyear DT 710	\$ 400.00	area by IH scout	
88	20.8-42R	2*	40%	Goodyear DT 7	\$ 400.00	area by IH scout	



## USED TIRE INVENTORY

<i>Lot#</i>	<i>Size</i>	<i>Ply</i>	<i>Tread %</i>	<i>Brand</i>	<i>Price</i>	<i>Notes</i>	<i>Origin</i>
95	20.8-42R	2*	30%	Goodyear DT 710	\$ 300.00	area by IH scout	
96	20.8-42R	10	40%	Firestone	\$ 400.00	in 42 inch dual area	
146	20.8-42R	157A8	40%	Firestone	\$ 900.00	on 18x42 JD rim by IH Scout	
170	20.8-42R	2*	20%	Goodyear	\$ 200.00		
185	21L-24	12	15%	MRF industrial	\$ 100.00	bare tire-off of 710 JD backhoe	
1	21L-28	10	20%	Goodyear backhoe	\$ 125.00	East end tractor yard by terrace gate	
12	21L-28	10	20%	Goodyear backhoe	\$ 125.00	East end tractor yard by terrace gate	
118	23.1-24	8	90%	Firestone 23 R1	\$ 500.00	bad spot on side wall, on L3 Gleaner	
34	23.1-26	10	50%	Powermark	\$ 500.00	On IH 1460 combine west end hay eq yard	
54	23.1-26	10	50%	Powermark	\$ 500.00	On IH 1460 combine west end hay eq yard	
127	23.1-26	10	60%	Powermark	\$ 600.00	On 915 IH combine	
128	23.1-26	10	60%	Powermark	\$ 600.00	On 915 IH combine	
131	23.1-26	10	50%	Goodyear	\$ 500.00	on 815 IH combine	
132	23.1-26	10	50%	Goodyear	\$ 500.00	on 815 IH combine	
202	23.1-26	12	75%	Galaxy	\$ 750.00	by 8630 JD on hillside	
203	23.1-26	12	75%	Galaxy	\$ 750.00	by 8630 JD on hillside	
294	23.1-26	10	40%	Goodyear	\$ 400.00	turf tread on 8h rim by scout	
295	23.1-26	10	40%	Goodyear	\$ 400.00	turf tread on 8h rim by scout	
194	23.1-30	8	65%	Goodyear	\$ 800.00	Next to 8630 JD on hillside	
237	23.1-30	10	25%	Goodyear	\$ 375.00	on 12 hole rim, on hillside	
238	23.1-30	8	75%	Powermark	\$ 975.00	on 12 hole rim, on hillside	
239	23.1-30	10	25%	Goodyear	\$ 375.00	No rim, on hillside	
9	23.1-34	8	70%	Firestone	\$ 1,000.00	on L3 combine thru 2nd gate on hillside	
40	23.1-34	8	70%	Firestone	\$ 1,000.00	on L3 combine thru 2nd gate on hillside	
98	24.5-32	10	60%	Good year deep tread	\$ 500.00	n.e. corner tractor yard on 10 hole rim	
99	24.5-32	10	60%	Good year deep tread	\$ 500.00	n.e. corner tractor yard on 10 hole rim	
113	24.5-32	10	40%	Goodyear Power Torque	\$ 500.00	on rim, behind 815 IH combine	
114	24.5-32	10	40%	Goodyear Power Torque	\$ 500.00	on rim, behind 815 IH combine	
115	24.5-32	10	30%	Goodyear Power Torque	\$ 250.00	cracked	



## USED TIRE INVENTORY

Lot#	Size	Ply	Tread %	Brand	Price	Notes	Origin
116	24.5-32	10	30%	Goodyear Power Torque	\$ 250.00	cracked	
123	24.5-32	10	40%	Goodyear	\$ 750.00	on N6 Gleaner	
124	24.5-32	10	40%	Goodyear	\$ 750.00	on N6 Gleaner	
141	24.5-32	10	50%	Goodyear	\$ 800.00	stubble damage, on 6620 JD combine	
142	24.5-32	10	50%	Powermark	\$ 800.00	stubble damage, on 1480 IH combine	
130	28L-26	10	70%	Goodyear	\$ 1,250.00	on 6620 JD combine	
174	31x13.5-15	10	75%	Traction Master	\$ 200.00	skidsteer tread	
175	31x13.5-15	10	75%	Traction Master	\$ 200.00	skidsteer tread	
147	320/90R42		20%	DT800 Goodyear	\$ 260.00	on silver Case IH rear wheels below terrace	
148	320/90R42		35%	DT800 Goodyear	\$ 350.00	on silver Case IH rear wheels below terrace	
155	320/90R42		30%	DT800 Goodyear	\$ 325.00	on silver Case IH rear wheels below terrace	
156	320/90R42		10%	DT800 Goodyear	\$ 125.00	on silver Case IH rear wheels below terrace	
200	320/90R42		30%	Firestone	\$ 325.00	on 8 hole rim next to 8630 JD on hillside	
201	320/90R42		20%	Firestone	\$ 260.00	on 8 hole rim next to 8630 JD on hillside	
292	320/90R46	148A8	45%	Firestone	\$ 550.00	on rim by scout	
293	320/90R46	148A8	45%	Firestone	\$ 550.00	on rim by scout	
180	380/80R38	142A8	95%	Michelin	\$ 350.00	by IH scout - needs tube (side wall cut)	
215	380/80R38		30%	Firestone	\$ 450.00		
26	380/90-50R	151A8	25%	Goodyear DT800	\$ 350.00	end	
27	380/90-50R	151A8	15%	Goodyear DT800	\$ 200.00	end	
28	380/90-50R	151A8	10%	Goodyear DT800	\$ 175.00	end	
29	380/90-50R	151A8	25%	Goodyear DT800	\$ 350.00	end	
150	460/85R38	149A8	75%	Firestone	\$ 750.00	No rim, on hillside	
264	460/85R38		90%	Continental	\$ 750.00	No rim, on hillside	CG
213	480/70R34	146A8	40%	Goodyear Sure Grip	\$ 650.00	on 34" waffle wheel, on hillside	
219	480/70R34	146A8	40%	Goodyear Sure Grip	\$ 650.00	on 34" waffle wheel, on hillside	
37	480/80-38R		99%	Goodyear ultra torque	\$ 1,250.00	No rim, west end by IH Scout	
22	480/80-46R		60%	Michelin	\$ 1,100.00	on Grey 10 rims, in 42" dual area, rims not included	

## USED TIRE INVENTORY

Lot#	Size	Ply	Tread %	Brand	Price	Notes	Origin
23	480/80-46R		60%	Michelin	\$ 1,100.00	on Grey 10 rims, in 42" dual area, rims not included	
55	480/80-50R		25%	Firestone	\$ 450.00	<b>one only</b>	
56	480/80-50R		25%	Firestone	\$ 450.00	<b>\$800</b>	
224	520/85R42	157A8	15%	Goodyear	\$ 250.00	bare tire	
229	520/85R42	157A8	30%	Goodyear	\$ 500.00	bare tire	
70	540/65R34	145A8	90%	Goodyear DT820	\$ 1,200.00	By scout off rim	
71	540/65R34	145A8	90%	Goodyear DT820	\$ 1,200.00	By scout off rim	
63	620/70-42R		40%	Michelin XM28	\$ 550.00	out rims	
64	620/70-42R		40%	Michelin XM28	\$ 550.00	out rims	
65	620/70-42R		50%	Goodyear DT820	\$ 650.00	without rims	
66	620/70-42R		50%	Goodyear DT820	\$ 650.00	without rims	
104	710/70R38	166 A8	25%	Goodyear DT820	\$ 795.00	by IH scout	
105	710/70R38	166 A8	25%	Goodyear DT820	\$ 795.00	by IH scout	
106	710/70R38	166 A8	25%	Goodyear DT820	\$ 795.00	by IH scout	
107	710/70R38	166 A8	25%	Goodyear DT820	\$ 795.00	by IH scout	
108	710/70R38	166 A8	25%	Goodyear DT820	\$ 795.00	by IH scout	
109	710/70R38	166 A8	25%	Goodyear DT820	\$ 795.00	by IH scout	
110	710/70R38	166 A8	25%	Goodyear DT820	\$ 795.00	by IH scout	
212	800/65R32		50%	Continental	\$ 1,250.00	by 8630 JD on hillside	
100	800/70R38	173 A8	95%	Goodyear DT820 Super Traction	\$ 3,500.00	Consigned	
101	800/70R38	173 A8	95%	Goodyear DT820 Super Traction	\$ 3,500.00	Consigned	
242							
243							
286							
284							
285							
220							

## USED TIRE INVENTORY

<i>Lot#</i>	<i>Size</i>	<i>Ply</i>	<i>Tread %</i>	<i>Brand</i>	<i>Price</i>	<i>Notes</i>	<i>Origin</i>
2							
11							
24							
91							
92							
93							
121							
154							
183							
184							
189							
190							
193							
209							
242							
288							
298							
299							
302							